SPE RESPONSE FO	OR CERTIFICATE OF CORRECTION
DATE : 9-9-04	Paper No.: 9-
TO SPE OF : ART UNIT 285/	
SUBJECT : Request for Certificate of Corr	rection on Patent No.: 6, 7/4,277
	accompanying request for a certificate of correction.
Please complete this form and return with Certificates of Correction Branch - Please Palm location 7580 - Tel. No. 305-8309	C 3-915
patent read as shown in the certificate of co	orrecting Office and/or Applicant's errors, should the orrection? No new matter should be introduced, nor should the
I FW (S. N. 09/8/8	e table of contents in 3,625
Thank You For Your Assistance	Certificates of Correction Branch
The request for issuing the above-ide Note your decision on the appropriate box.	entified correction(s) is hereby:
Approved	All changes apply.
☐ Approved in Part	Specify below which changes do not apply.
☐ Denied	State the reasons for denial below.
Comments:	

SPE

Art Unit U.S. DEPARTMENT OF COMMERCE Patent and Trademark Office

PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,714,277 B2

DATED

: March 30, 2004

INVENTOR(S): Shinichi HARA et al.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 53, "On" should read -- At --.

Line 55, "On" should read -- At --.

COLUMN 2:

Line 13, "a vessel which airtightly" should read -- an airtight vessel which --.

COLUMN 18:

Lines 25-30 should be deleted.

Line 62, "influence" should read -- influences --.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,714,277 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page

PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,714,277 B2

DATED

: March 30, 2004

INVENTOR(S): Shinichi HARA et al.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20:

Line 37, "vender" should read -- vendor --.

Line 40, "vender," should read -- vendor, --.

COLUMN 24:

Line 25, "camber" should read -- chamber --.

Line 46, "whererin" should read -- wherein --.

Line 67, "displacement," should read -- displacement, and --.

COLUMN 25:

Line 16, "via movable" should read -- via a movable --.

Line 21, "said" should read -- wherein said --.

Line 25, "wherein" should read -- wherein the --.

MAILING ADDRESS OF SENDER:

FORM PTO 1050 (REV. 3.82)

PATENT NO. 6,714,277 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

11 2 JUL 2004

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,714,277 B2

DATED

March 30, 2004

INVENTOR(S): Shinichi HARA et al.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Approved 9-9-04

COLUMN 26:

Line 12, "manufactoring" should read -- manufacturing --.

Line 37, manufactoring" should read -- manufacturing --.

Line 41, the second occurrence of "in order" should be deleted.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,714,277 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page